

 <p>पब्लिक वर्क BUILDING IS A ROAD</p>	 <p>एक बंदम स्वच्छता की ओर</p>		<p>Executive Engineer, Provincial Division, Hr.PWD B&amp;R Br., Majri Chowk, Panchkula (Tel.No.:- 0172-2920477) E-mail:- <a href="mailto:pwd-eeepd-panchkula@hry.nic.in">pwd-eeepd-panchkula@hry.nic.in</a></p>
---	---	---	---

If correct letter File 27.11.2024

To

The Principal,  
Doon Public School,  
Site No. II & III, Sec.21, Panchkula

Memo No. 2361

Dated: 07/05/2025

**Subject:-** Request for building safety certificate of Doon Public Schol, Site No. II & III, Sector 21, Panchkula.


**Ref:-** Your office memo No. DPS/P/23B/7350/25-26 dated 28.04.2025.

In this connection, it is intimated that Block (1) Lower Ground + G + 3 and in Block (2) G+ 2 of subject cited school has been inspected by the Sub Divisional Engineer, PSD No.IX, Panchkula alongwith Junior Engineer concerned as reported by him vide his memo No. 108 dated 05/05/2025, during inspection of site, no visual stresses have been noticed in the existing structure.

Accordingly as per report submitted by the concerned Sub Divisional Engineer as well as consultant, the Structural Stability Certificate is hereby issued for the session 2025-26.

Note:- Our department does not issue any certificate regarding safety from earthquake.

DA/NIL

  
Executive Engineer,  
Provl. Divn., Hr.PWD B&R ,  
Panchkula

  
**PRINCIPAL**  
**Doon Public School**  
Sector-21, Panchkula HR

  
**MANAGER**  
**Doon Public School**  
Sector-21, Panchkula HR

## BUILDING SAFETY CERTIFICATE

No. RA/STR/2024/1422

Dated: 09/09/2024

It is certified that the existing building DOON PUBLIC SCHOOL  
at SITE NO. II & III, SECTOR-21, PANCHKULA (HR.) is  
having block(s) / Floor(s) as per details below:

Details of Block(s) in school	Block (1)	Block (2)
No. of floor(s) in the Block	LOWER GROUND + G+3	G+2

The building is owned/occupied by DOON PUBLIC SCHOOL, SECTOR-21,  
PANCHKULA have complied with the Building safety requirements in  
accordance with National Building code Rules, and verified by the officers concerned of  
RAKHRA ASSOCIATES (Name of Department / Govt.) on 29/08/2024  
(date of inspection) in the presence of CAPT. SANJAY ANAND, SM.  
MANAGER, DOON PUBLIC SCHOOL (name and addresses of the Manager/Secretary  
or his representative) and that the building/premises is fit for occupancy for running school  
with effect from 31/08/2024 for a period of two years in accordance  
with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 09/09/2024 at CHANDIGARH by

  
PRINCIPAL  
Doon Public School  
Sector-21, Panchkula HR

  
MANAGER  
Doon Public School  
Sector-21, Panchkula HR

Signature with Seal :

Name : ER. SHERRY RAKHRADesignation : CONSULTING ENGINEER

Name &amp; Address of Department/ Office:

# 2500, SECTOR - 40C,  
CHANDIGARH

  
ER. SHERRY RAKHRA  
CHARTERED STRUCTURE ENGINEER  
M.E. STRUCTURES (HONS.)  
M.I.S.E., M.I.C.I., A.M.I.O.V., M.S.E.F.  
M.I.E. - M-1727308